

cforce mini RF SUP 1.2.18

Software Update Package cforce_minRf-1.2.18_r12278.cmf

RELEASE NOTES

Date: September 9th, 2019

Table of Contents

A. Introduction	3
B. Update Instructions	3
How to get a Software Update Package	3
cforce mini RF Update Procedure	3
Update with WCU-4	3
C. Bug Fixes	3
Lens File Transfer - Source Motor	3
cforce mini RF Wrong Bootloader Version After Update	4
Rebooting issues with CAM connector	4
Motor failure on RED	4
Passive Mode on ALEXA Mini Mount	4
No Motor Limits with Pre-marked Ring	4
Unable to trigger REC on RED cameras	4
Motor Dropouts	4
Master/Client Switch Issue on ALEXA Mini	4
cforce mini RF Reboot on EXT	4
Cooke/i on AMIRA Missing Infinity Mark	4
Cooke/i on AMIRA Missing Lens Model Indication	4
Cooke/i Lens Mapping Malfunction on AMIRA	4
Calibration Range Offset After Skipping	4
LEDs Out of Sync	4
WCU-4 Freeze After Power-Cycle and Resend File	4
D. Known Issues	5
Lens Source Switch - No Scale Present on WCU-4	5
Motor Randomly Starts to Calibrate	5
Offset Issue with ALEXA EV	5
Focus Offset Not Indicated After Reboot	5
Focus Offset Not Applicable on Lens File	5
ALEXA EV Unavailable ND Filter Is Displayed	5
Double Assignment	5
Temperature Shutdown	5
Missing Lens Data in Client Mode	5
Tally Glitch with Sony Cameras	6

A. Introduction

We herewith announce the release of the Software Update Package (SUP) 1.2.18 for the cforce mini RF. This is an important maintenance release. We highly recommend updating the cforce mini RF to this Software Update Package. Please take your time to go through this document before you start using the cforce mini RF. For more information, please visit <https://www.arri.com/en/technical-service/firmware/software-updates-ecs/software-update-for-cforce-mini-rf>

B. Update Instructions

How to get a Software Update Package

Go to the ARRI website <https://www.arri.com/en/technical-service/firmware/software-updates-ecs/software-update-for-cforce-mini-rf> and download the latest Software Update Package (SUP).

cforce mini RF Update Procedure

The current software update can be applied to the cforce mini RF via WCU-4.

Update with WCU-4

Precautions

During the update, supply the cforce mini RF with >12V Voltage, e.g. by using the Cable CAM (7p) – D-Tap (K2.0018813) connected to a battery with D-Tap interface.

Preparing the SD Card

Have a FAT16 or FAT32 formatted SD/SDHC card up to 32GB for updating. Copy the cforce mini RF Software Update Package into the root folder of the SD/SDHC card.

Performing the Update

1. Connect WCU-4 and cforce mini RF with Cable LCS – LBUS (K2.0007318 or K2.0013044).
2. Connect cforce mini RF to 12V power source e.g. with Cable CAM (7p) – D-Tap (K2.0018813)
3. Turn the WCU-4 on.
4. Insert the SD card into the SD card slot of the WCU-4.
5. Go to MENU > FIRMWARE > LBUS Update.
6. Select the cforce mini RF as LBUS device.
7. Choose the desired Software Update Package and then press the two UPDATE soft buttons simultaneously to start the update.

Caution: Do not remove the SD card during the update!

The update process takes several seconds.

C. Bug Fixes

This is a list of bug fixes for this particular SUP 1.2.18 Software Update Package.

Lens File Transfer - Source Motor

Fixed a bug where lens data source would remain set to camera after the same lens file has been sent from WCU-4 the second time.

cforce mini RF Wrong Bootloader Version After Update

Fixed a bug where the displayed software version of the bootloader is lower than the update performed.

Rebooting issues with CAM connector

Fixed a bug where the cforce mini RF would sequentially reboot or have a malfunction with REC start/stop when connected to another device via CAM connector.

Motor failure on RED

Fixed a bug where the cforce mini RF would not work when connected a RED camera's CTRL port.

Passive Mode on ALEXA Mini Mount

Fixed a bug where the cforce mini RF remain in passive mode when connected to the ALEXA Mini LBUS lens mount via CAM-LBUS cable.

No Motor Limits with Pre-marked Ring

Fixed a bug where motor limits would not apply during lens mapping to a pre-marked ring.

Unable to trigger REC on RED cameras

Fixed a bug where recording on a RED camera would not be triggered.

Motor Dropouts

Fixed a bug where the motor would drop out and request re-calibration.

Master/Client Switch Issue on ALEXA Mini

Fixed a bug where the motor would not be controllable after switching it from master to client when connected to ALEXA Mini/WCU-4.

cforce mini RF Reboot on EXT

Fixed a bug where the motor would reboot when powered via CAM (6p) cable.

Cooke/i on AMIRA Missing Infinity Mark

Fixed a bug where the infinity mark from Cooke /i lenses connected to AMIRA would not show up on WCU-4.

Cooke/i on AMIRA Missing Lens Model Indication

Fixed a bug where the lens model name from a Cooke /i lens connected to AMIRA would not show up on WCU-4.

Cooke/i Lens Mapping Malfunction on AMIRA

Fixed a bug where lens mapping to a pre-marked ring would be applicable, even without a lens file.

Calibration Range Offset After Skipping

Fixed a bug where calibration would be off after power-cycling and skipping the CAL request.

LEDs Out of Sync

Fixed a bug where the LEDs on two daisy-chained cforce mini RF motors would not be synchronized.

WCU-4 Freeze After Power-Cycle and Resend File

Fixed a bug where the WCU-4 would crash after transferring a lens file, power-cycling the cforce mini RF, and trying to re-send the same file after the reboot.

D. Known Issues

This is a list of known issues for this particular SUP 1.2.18 Software Update Package.

Lens Source Switch - No Scale Present on WCU-4

Switching the lens data source from LDA (cforce mini RF) to LDS (camera), on cameras not providing lens data via CAM connector (RED, SONY) leads to lens data artefacts (numeric iris vales) or no lens data at all.

Workaround: Reboot of the WCU-4 solves the issues.

Motor Randomly Starts to Calibrate

In rare occasions, the motor can randomly start to calibrate. This can be caused by radio interference from near-by handsets.

Offset Issue with ALEXA EV

Applying a focus offset on WCU-4 may not work correctly with the cforce mini RF connected to ALEXA EV's EXT port and an LDS lens used.

Focus Offset Not Indicated After Reboot

When setting an offset with the WCU-4 on the focus axis and reboot the motor, offset is still applied, but not indicated on the WCU-4.

Focus Offset Not Applicable on Lens File

When loading a lens file on the motor and trying to set an offset on the focus axis with the WCU-4, it is not possible to set a focus offset.

ALEXA EV Unavailable ND Filter Is Displayed

When connecting a cforce mini RF motor to the EXT connector on an ALEXA EV camera (11.1.1) and checking EI in the camera setup, the middle-top user button displays the assignment ND ON/OFF even if there is no ND filter in the camera.

Double Assignment

Connecting two hand units on the same radio channel to cforce mini RF and assigning them to the same axis can very rarely lead to severe motor jitter. Please make sure to not assign two hand units to the same axis, e.g. by disabling iris on WCU-4 if iris is controlled from an SXU-1.

Temperature Shutdown

Continuously operating the motor at high friction for a several minutes will cause a temperature shutdown, manifesting in reduced motor speed. Cooling down the motor will solve the issue.

Missing Lens Data in Client Mode

A cforce mini RF set to Client mode will not transmit LDS lens data from camera to LBUS devices such as Master Grips. Example Setup: AMIRA EXT (providing LDS lens data) > cforce mini RF (Client mode) > Master Grip (no lens data available).

Workaround: Connect Master Grips directly to camera: AMIRA EXT (providing LDS lens data) > Master Grip (lens data available) > cforce mini RF (Client mode).

Tally Glitch with Sony Cameras

If the cforce mini RF and a Sony F-series or Venice camera is powered up, and the connection between motor and camera will be established afterwards, then REC>STBY>REC tally is indicated on the WCU-4 hand unit after pressing REC for the first time on the WCU-4.