L5 & L7
Firmware Version: 2.05.0

KNOWN ISSUE REPORT

Know Issues: FW Version: 2.05.0

Issue	Consequence	Estimated Completion Date
L7-C without control panel update issue	It could be possible that an update to firmware 2.5 does not work with an L7-C model without control panel. To resolve the issue, power cycle the fixture after fixture is connect to ALSM.	2019

ALSM: (ARRI Lighting Software Manager) PC application for updating firmware and setting attributes of ARRI LED fixtures.

DMX: Communication protocol designed for lighting fixtures in the film, TV and live entertainment markets

RDM: (Remote Device Management) Two-way communication protocol designed to read and set attributes of a light fixture

NOTES:
- Read all warnings and notices in the L-Series User Manual.