



**L5 L7**

**Firmware Version: 2.5.2**

KNOWN ISSUE REPORT

## Known Issues: FW Version: 2.5.2

| Issue                | Consequence  | Estimated Completion Date |
|----------------------|--|---------------------------|
| L5 CCT setting issue | At CCT mode, could be that certain CCT range cannot be set via control panel encode. | Next Update               |

**ALSM:** (ARRI Lighting Software Manager) PC application for updating firmware and setting attributes of ARRI LED fixtures.

**DMX:** Communication protocol designed for lighting fixtures in the film, TV and live entertainment markets

**RDM:** (Remote Device Management) Two-way communication protocol designed to read and set attributes of a light fixture

### NOTES:

- Read all warnings and notices in the L-Series User Manual.