

ARRI Lighting Service Manager Release history

LIGHTING - TECHNICAL INFORMATION



os	Version	Build	Release Date	Changes
WIN				ALSM Version for LiOS 3.1 Orbiter ALEXA calibration files are hosted on the ALSM backend server
MAC	5.5.2	26068	2024-05-02	 ALSM shows a maintenance symbol in the device tree, if the connected Orbiter needs a calibration file update for LiOS 3.1 Upload of ALEXA calibration files to Orbiters Bug fixes
WIN				 LiOS fixtures Light Engine Channel Check LiOS fixtures Light Engine Lookup Test Offline service log interpreter Offline error log reader
MAC	5.5.1	26030	2024-02-22	 Filter function for error logs Show syslog details for selected error log line Added latest SkyPanel Classic Remote Control software Bug fixes
WIN MAC	5.4.0	25974	2024-01-22	Bug fix: LiOS 3.0.12 removed and LiOS 3.0.13 added
WIN	5.4.0	25969	2024-01-17	 Added SkyPanel X Support Added LiOS 3.0 for SkyPanel X Manual connection of fixtures in an IP range Improvements for dark mode
MAC				 Bug fix: Multi unit update for LiOS devices Bug fix: Finding fixtures via bonjour in the network
WIN	5.3.2	25802	2023-03-07	 Added Orbiter beam optics Bug fix: Added missing DFU software module
MAC				
WIN	5.3.1	25799	2022-12-23	 Release for SkyPanel firmware V4.4.0 Includes SkyPanel firmware V4.4.0 Added DMX user presets export and import
MAC]			Bug fixes
WIN				 Release for Orbiter firmware LiOS V2.0.2 Expert mode: Orbiter optics motor calibration and test run added Read service log for multiple SkyPanels or Orbiters Added keyboard shortcut Ctrl+I for identify
MAC	5.3.0	25789	2022-08-25	 Added sorting by IP address in the device list Includes latest SkyPanel firmware V4.3.2 Includes latest Orbiter firmware V2.0.2 Added Orbiter DMX V5.0 specification Orbiter firmware update: User can choose star or chain wiring Bug fixes



WIN	5.2.0	25727	2022-04-29	 Release for Orbiter firmware LiOS v1.4.3 Includes latest L5/L7 firmware ALSM is now notarized and therefore renamed to "alsmApp" Appearance of the fixtures in the device tree can be set in the ALSM preferences (snr or IP address) Expert Mode includes writing barcode and type to optics (Available for special Orbiter firmware)
WIN				 Expert Mode for writing Orbiter fixture bar code Bug fixes Release for Orbiter Firmware LiOS v1.2.1
MAC	5.1.0	25650	2021-05-06	 User can skip import of network settings during import to multiple Orbiters Switched to Qt 5.15.1 Orbiter USB connection added Improved Service Log for Orbiters Added "Save Device Log" for saving a tar.gz archive Mail log changed: Attachments are used Hide "Colour Sensor Calibration" Bug fixes
WIN	5.0.0	25563	2020-09-30	 Release for Orbiter Firmware 1.0.5 General support for Orbiter Includes the latest firmware components for all supported fixtures except the orbiter firmware Firmware installation to multiple Orbiters is supported Bug fixes
WIN	4.2.0	25339	2019-04-11	 Release for SkyPanel Firmware 4.2 Added Light Engine Compensation in GUI and function
IVIAU				Pologo for ChuPonel Cimenus 4.4
WIN	_			 Release for SkyPanel Firmware 4.1 Includes FW 4.1 Improved GUI functionality
MAC	4.1.0	24942	2018-11-14	 Added display, bonjour and extended colour control settings Group view is blocked during batch processes Stability improvement Fixed Bugs
WIN	3.2.0	21930	2018-02-07	 Release for SkyPanel Firmware V3.2 General support for S360-C Includes FW 3.2 for S360-C
MAC				Includes Bootloader for S360-CFixed Bugs



WIN	3.0.0	18069	2017-04-24	 Release for SkyPanel Firmware V3.0 Multi Selection of SkyPanels Change of all settings in the GUI will be applied to all selected SkyPanels, if applicable Batch-import of json-settings-file to all selected SkyPanels (only allowed for same type; -C or -RP) UI for changing the webserver password configuration for SkyPanels with firmware release 3.0 Update functionality for SkyPanel Remotes Type of DFU device can be selected during
MAC				registration (Bootloader update of SkyPanel or Firmware Update of SkyPanel Remote) DMX implementation table V4.3 IP-Connect-Dialog with new functionality Reset error state for selected devices Fixed bugs Added latest firmware components for SkyPanel and SkyPanel Remote
WIN	2.2.1	15611	2016-10-19	 S120 support DMX Implementation Table V4.2 Location for firmware data in <commonappdata></commonappdata> Automatic search for updates on ARRI-Server On Max OS X the software is delivered as Installer Package
WIN	2.2.0	13605	2016-04-15	 Includes L10 and Skypanel Firmware v2.5.0 General bug fixing & stability improvement Includes L7/ L5 firmware v2.0.5 Includes L10 firmware v2.0.0 Includes SkyPanel Firmware v2.0.0 Implemented automatic software update Implemented export and import of presets and
MAC				 Implemented export and import of presets and settings for SkyPanel On Max OS X the software is delivered as Installer Package
WIN MAC	2.1.0	11634	2015-12-04	 General bug fixing & stability improvement Implemented support for ARRI SkyPanel Implemented update of boot loader for L10
WIN MAC	2.0.0	7213	2015-04-13	First public release