


Ultrasonic Distance Measure UDM-1



Configuration Overview | 4.1.0 / 2020.02

UDM-1 Distance Measure

Ultrasonic Distance Measure UDM-1 Set
K0.60055.0
Set includes:
UDM Sensor Unit, K2.65130.0
UDM Display Unit, K2.65131.0
Cable UDM-Sensor, K2.0006459



PSC Power Cable



PSC Cable System:
Both needed:
PSC cable to device
PSC power cable to power source

ARRI PSC power supply cables

K2.65206.0 PSC-XLR3	1,5m/5ft	1,5m/5ft	24 Volts battery
K2.65207.0 PSC-XLR4	1,5m/5ft	1,5m/5ft	12 Volts battery
K2.65211.0 PSC-RS	0,6m/2ft	0,6m/2ft	ARRI RS socket
K2.65212.0 PSC-FI2	0,6m/2ft	1,5m/5ft	ARRI OBB-2 battery

Cable UDM-UMC (1,5m/5ft)
K2.65144.0 (yellow cable)

Connects to CUB-1



LBUS 0.2m/8", K2.0006749
LBUS 0.3m/1ft, K2.0006750
LBUS 0.5m/1.5ft, K2.0006751
LBUS 0.8m/2.5ft, K2.0006752
LBUS 1.5m/5ft, K2.0006753
LBUS 3m/10ft, K2.0006754
LBUS 6m/20ft, K2.0006755
LBUS 15m/49ft, K2.0006756



cforce motors



ALEXA Mini /
ALEXA Mini LF

Cable UDM-ALEXA (1,5m/5ft)
K2.65261.0 (yellow cable)
Connects to EXT socket of ALEXA
cameras with SUP 8.0 or later



UDM values / Lens Data

Focus Tracking

WCU-4



Wireless Compact Unit
WCU-4, K2.72103.0

Focus Tracking

UDM values / Lens Data

Cable UDM-UMC (1,5m/5ft)
K2.65144.0 (yellow cable)



Connects to UMC-4



UDM values / Lens Data

Focus Tracking



Cable UDM-RS (1,5m/5ft)
K2.65240.0 (yellow cable)
Connects to camera RS socket



any camera
with RS



SMC/EMC/AMC to RS, K2.0001606

UDM values /
no Lens Data

Cable UDM-D.Tap (0,8m/2,6ft)
K2.0023553



LBUS 0.2m/8", K2.0006749
LBUS 0.3m/1ft, K2.0006750
LBUS 0.5m/1.5ft, K2.0006751
LBUS 0.8m/2.5ft, K2.0006752
LBUS 1.5m/5ft, K2.0006753
LBUS 3m/10ft, K2.0006754
LBUS 6m/20ft, K2.0006755
LBUS 15m/49ft, K2.0006756



LBUS LBUS

