


## Macro Exposure Guide for S35mm

Approximate Exposure Increase in Stops



1. Place scale in object plane
2. Align blue line with left edge of frame
3. Read off values at right edge of frame
4. This chart is an approximation and should be used as a guide only

**FOR THE GUIDE TO WORK THIS LINE MUST BE 180(+/-1)MM LONG  
DO NOT USE 'FIT TO PAGE' OR 'SHRINK TO FIT' WHEN PRINTING**