



L10

Firmware Version: 2.5.5

KNOWN ISSUE REPORT

Date: 13-Dec-19



**Know Issues: FW Version: 2.5.5** 

Issue	Consequence	Estimated Completion Date
0 0	Light engine version information may be read out not correctly in log file and ALSM UI.	Next Update

**ALSM:** (ARRI Lighting Software Manager) PC application for updating firmware and setting attributes of ARRI LED fixtures.

**DMX:** Communication protocol designed for lighting fixtures in the film, TV and live entertainment markets

**RDM:** (Remote Device Management) Two-way communication protocol designed to read and set attributes of a light fixture

## NOTES:

- Read all warnings and notices in the L-Series User Manual.